

定中心表

暢銷
產品




2385-3



- 安裝在鑽床和銑床上,可快速準確地找到工件的中心
- 最大轉速建議不要超過800RPM

型號

2385-3



測頭	測量直徑	精度
P1	Ø0-60mm	0.015mm
P2	Ø0-160mm	0.02mm
P3	Ø0-250mm	0.03mm
P4	Ø3.2-80mm	0.015mm
P5	Ø3.2-180mm	0.02mm
P6	Ø3.2-280mm	0.03mm
P7	Ø0-2.8mm	0.015mm